UNITED STATES DISTRICT COURT DISTRICT OF MASSACHUSETTS

CHARLES BRETT, BUILDING INSPECTOR OF TOWN OF HAMILTON, Plaintiff,) C.A. No. 05-11542 RGS)
, V.))
IRINA V. TEMKINA,)
Defendant.))

AFFIDAVIT OF DONNA BREWER MacKENNA

- 1. I am the attorney for plaintiff Charles Brett, Building Inspector of the Town of Hamilton and a member of the bar of this court.
- 2. This affidavit is submitted in support of plaintiff's Motion for Partial Summary Judgment.
- 3. Exhibit A is a true and correct copy of the State Building Code Appeals

 Board Appeal Application Form filed by Irina V. Temkina and dated November 9, 2005.
- 4. Exhibit B is a true and correct copy of the report of the Hamilton Fire Department dated February 28, 2006.
- 4. Exhibit C is a true and correct copy of the decision of the State Bulding Code Appeals Board dated April 6, 2006.
- 5. All of these documents were produced to me by the Deputy General Counsel of the Department of Public Safety in response to a request for production under the Public Records Act, G.L. c. 66, § 5A. See the true and accurate copy of the letter of

Todd M. Grossman, Deputy General Counsel, dated March 7, 2006, attached as Exhibit D.

SIGNED UNDER PENALTIES OF PERJURY THIS 20TH DAY OF OCTOBER, 2006.

/s/ Donna Brewer MacKenna
DONNA BREWER MacKENNA

6134.22/396049

EXHIBIT A



The Commonwealth of Massachusetts

	partment of Public <u>Safety</u>
Board of Bu	ilding Regulations ma Scatedards
THE STATE OF THE S	
On	e Ashburton Place, Room 1801 _{NOV} 1 4 2005
Bos	ston, Massachusetts 02108-1618
	Phone (617) 727-7532 DEPARTMENT OF PUBLIC SAFETY
	Fax (617) 227-1754
STATE USE ONLY	STATE BUILDING CODE APPEALS BOARD
Fee Received: 150,00	APPEAL APPLICATION FORM
Received By: PBamy	
0.5	
DOCKET NUMBER: U5-105	DATE: 11/9/05
State Use Only	46
•	of Building Regulations and Standards from the decision of the:
Building Official from the City/Town of: Hami	
Board of Appeals from the City/Town of:	100
board of Appeals from the City/ Town of.	
Other Municipal Agency/Official entitled:	
Other Municipal Agency/Official entitled:	
Other Municipal Agency/Official entitled:	
Other Municipal Agency/Official entitled: State Agency/Official entitled:	
State Agency/Official entitled:	
State Agency/Official entitled:OTHER:	·
State Agency/Official entitled:OTHER:	received by appellant on 909 126 105 (see atta
State Agency/Official entitled: OTHER:*Order Dated:September 15 2005	
State Agency/Official entitled: OTHER: *Order Dated: September 15 2005 Interpretation O Order My Requirem	received by appellant on 909 \$26 \$05 (see acts, having been aggrieved by such (check as appropriate) attached ent o Direction o
State Agency/Official entitled: OTHER: *Order Dated: September 15 2005	received by appellant on 909 \$26 \$05 (see acts, having been aggrieved by such (check as appropriate) attached ent o Direction o
State Agency/Official entitled: OTHER: *Order Dated: September 15 2005 Interpretation O Order My Requirem Failure to Act O Other O Explain	received by appellant on 909 126 105 (see arts, having been aggrieved by such (check as appropriate) attached ent o Direction o
State Agency/Official entitled: OTHER: *Order Dated: September 15 2005 Interpretation O Order My Requirem Failure to Act O Other O Explain (This section must be completed or the application of the the applic	received by appellant on 909 \$26 \$05 (see atto , having been aggrieved by such (check as appropriate) attached ent o Direction o
State Agency/Official entitled: OTHER: *Order Dated: September 15 2005 Interpretation O Order Requirem Failure to Act O Other O Explain (This section must be completed or the application of the building structure been the subject of an application, yes, please indicate the date of the previous appearance.	received by appellant on 909 \$26 \$05 (see attached, having been aggrieved by such (check as appropriate) attached attached ent o Direction o will be returned.) ppeal by this or any other appeals board previous to this filing? al, whether the matter was heard before a local or state appeals
State Agency/Official entitled: OTHER: *Order Dated: September 15 2005 Interpretation o Order p Requirem Failure to Act o Other o Explain (This section must be completed or the application of the building structure been the subject of an application, yes, please indicate the date of the previous appears	received by appellant on 909 \$26 \$05 (see attached, having been aggrieved by such (check as appropriate) attached attached ent o Direction o will be returned.) ppeal by this or any other appeals board previous to this filing? al, whether the matter was heard before a local or state appeals ecifics of the decision (i.e. a variance was granted\not granted).

All appropriate code sections that are a subject of the appeal must be identified. All written supporting documentation must be submitted with this application. However, the Board reserves the right to continue the proceeding if such material warrants extensive review.

moke d

Places volum and ballons to
SIGNATURE OF APPELLANT/REPRESENTATIVE NAME - PLEASE PRINT)
Irina V. Temkina
Owner
APPELLANT'S CONNECTION TO SUBJECT PROPERTY:
Southe Hamilton, MA 01982
<u> </u>
ADDRESS OF SUBJECT PROPERTY:521 Bridge Street
Telephone No. (860) 597-3020 Fax Number: (860) 52337989
Telephone No. (860) 597-3020 Fax Number: (860) 52337989
old Lyme, CI 003/1
01d Lyme, CT 06371
ADDRESS FOR SERVICE: 125 Neck Road, P.O. Box 4017
REPRSENTING: Self
APPELLANT: Irina V. Temkina
bedrooms of the dwelling)
detectors (i.e. hold that smoke detectors are not required in the
Building Code. Hold that the dwelling has an adequate number of sm
Hold that the front stairs and railings are in compliance with the
State briefly desired relief (additional information may be attached if space is not sufficient):

Please return applications to:
Program Manager, Board of Appeals
Board of Building Regulations and Standards
One Ashburton Place, Room 1301
Boston, MA 02108-1618

DESCRIPTION OF BUILDING OR STRUCTURE RELATIVE TO THE MASSACHUSETTS STATE BUILDING CODE (7th EDITION): (Check as appropriate)

If the building is a One or Two Family Dwelling proceed to section entitled "Brief Description of the Proposed Work". Do not complete the tables below for one and two family dwellings.

New Construction	Existing Building	Repair(s)		Alteration(s)		Addition
Accessory Bldg.	Demolition	Other S ₁	pecify:			
Brief Description of Pro	posed Work:	Market Service Control of the Contro				
				······································		
	,					· · · · · · · · · · · · · · · · · · ·
USE GROUP AND CO	NICTRIICTION TVDE					
COL GROOT AND CO	•	Check as applicable)			CON	ISTRUCTION TYPE
A Assembly	A-1	A-2	F	1-3	1Å	
	A-4	A-5			1B	
B Business					2A	
E Educational					2B	
F Factory	F-1	F-2			2C	
H High Hazard		**************************************			3A	
I Institutional	I-1	I-2	I	-3	3B	
M Mercantile			***************************************		4	
R Residential	R-1	R-2	R	-3	5A	
S Storage	S-1	S-2			5B	
U Utility	Specif	y:		<u>L</u>		
M Mixed Use	Specif					
S Special Use	Specif	y:		•		
COMPLETE THIS S	SECTION IF EXISTING		OING RENOV	ATIONS, ADDIT	ONS AND/	OR CHANGE IN USE
Existing Use Group:			7	Group:		
Existing Hazard Index (7	780 CMR 34):	******		ard Index (780 CI		
BUILDING HEIGHT A	ND AREA					
BUILDING		Existing (if	applicable)		P	roposed
Number of Floors or stor basement levels	ies include					
Floor Area per Floor (sf)						
Total Area (sf)						
Total Height (ft)						
Brief Description of t	the Proposed Worl	<u>c:</u>				
N/A No prop	osed work.					

STATE BUILDING CODE APPEALS BOARD - SERVICE NOTICE

I,Irina V. Temkina	, as		xiv the
Appellant/Petitioner		in an appea	l filed with the State
Building Code Appeals Board on11/	<u>'9/ </u>	20 25	
HEREBY SWEAR UNDER THE PAINS AN PROCEDURES ADOPTED BY THE STA AND SECTION 122.3.1 OF THE STATE BUOF THIS APPEAL APPLICATION ON THE	TE-BOARD-OF-BUILE JILDING CODE, I SERV	DING REGULATIONS A VED OR CAUSED TO BE	ND STANDARDS SERVED, A COP
NAME AND ADDRESS OF PERSON/AGENCY SERVED	METHOD OF SER	VICE DA	ΓΕ OF SERVICE
<u>Deb Paskowski, Assistant</u> Charles Brett	to In Pers	on 11	/8/05
		A-000000000000000000000000000000000000	
			
Signature APPELLANT/PETITIONER			
,			
On the North Day of A	Javenber	20 <u>0</u> PERSON	IALLY APPEARED
	EINA Tember be or Print the Name of the App	Nタ ellant)	
AND ACKNOWLEDGED AND SWORE TI	HE ABOVE STATEMEN	ITS TO BE TRUE.	NICHAEL KILMARTIN III
		Commonv My Co	IIOTACL NEWARTH III Iotary Public vealth of Massachusetts mmission Expires Uly 18, 2012
NOTARY BURNIC		MY COMMISSION :	

Irina V. Temkina

125 Neck Road, Post Office Box 4017, Old Lyme, Connecticut 06371

Telephone/Facsimile: (860) 597-3020 E-mail: irina.temkina@uconn.edu

Re: Temkina v. Town of Hamilton Building Inspector

Dwelling: 521 Bridge Street, South Hamilton

Date of Order: September 15, 2005


Date Order Received: September 26, 2005

AFFIDAVIT WITH RESPECT TO RECEIPT OF BUILDING OFFICIAL'S ORDER

I, Irina V. Temkina, state that I received the Hamilton Building Inspector's order dated September 15, 2005 on September 26, 2005. I had been out-of-state, and was not able to review my mail until September 26, 2005.

Sworn to under pains and penalties of perjury this day of November of the year 2005.

Irina V Temkina



Irina V. Temkina

125 Neck Road, Post Office Box 4017, Old Lyme, Connecticut 06371

Telephone/Facsimile: (860) 597-3020 E-mail: irina.temkina@uconn.edu

November 8, 2005

Re: Temkina v. Town of Hamilton Building Inspector

Dwelling: 521 Bridge Street, South Hamilton

Date of Order: September 15, 2005

Date Order Received: September 26, 2005

MEMORANDUM IN SUPPORT OF APPEAL

This memorandum is submitted in support of the State Building Code Appeals Board Appeal.

On September 26, 2005, I received a communication dated September 15, 2005 from the Town of Hamilton Building Inspector, Charles Brett. The communication is attached hereto as Exhibit A. The communication alleged several "code violations." The following constitutes the basis for my appeal of Mr. Brett's order.

L. The Dwelling's Front Stairs and Railing Do Not Violate the Building Code

Mr. Brett alleges that "the front stairs from egress [are] improper...[t]he risers are of non-uniform height and too short. The top step has epoxy affixed to it that constitutes a tripping hazard...[t]he skim coat on the top step was improperly installed. The nosing represents a tripping hazard. The railing is particularly dangerous, with spacing of the balusters out of code, excessive spacing between the bottom of the railing and the top of the stairs, and bolts loose and inadequate, so that the entire railing can easily be wiggled and is inadequate to support someone's weight."

Mr. Brett also alleges that "when I conducted a viewing of the property last August, I observed the front stairs to be in an unacceptably dilapidated state, in violation of the state building code."

I dispute these allegations for the following reasons.

a. Mr. Brett did not allege that the front stairs "were in an unacceptably dilapidated state" or "in violation of the state building code" during his August 2004 inspection.

Communication concerning the results of the August 2004 inspection is attached hereto as Exhibit B.

- b. The dwelling was inspected by a HUD Housing Quality Standards inspector Stephen Bento on February 23, 2005 and the steps and railing were found to be in repair. Affidavit of HUD Inspector is attached hereto as Exhibit C.
- c. The dwelling was inspected by a HUD Housing Quality Standards inspector Leo Panunzio on August 9, 2005 and the steps and railing were found to be in repair. HUD re-inspection report is attached hereto as Exhibit D.
- d. An independent inspection confirms that the stairs satisfy 780 CMR 3603.13.2, Treads and risers:

"The maximum riser height shall be 8-1/4 inches (210 mm) and the minimum tread depth-shall be nine inches (229 mm). The riser height shall be measured vertically between leading edges of the adjacent treads. The tread depth shall be measured horizontally between the vertical planes of the foremost projection of adjacent treads and at a right angle to the tread's leading edge. The walking surface of treads and landings of a stairway shall be sloped no steeper than one unit vertical in 48 units horizontal (2% slope). The greatest riser height within any flight of stairs shall not exceed the smallest by more than 3/8 inch (9.5 mm) and any two successive risers shall not deviate by more than 3/16-inch in height. The greatest tread depth within any flight of stairs shall not exceed the smallest by more than 3/8 inch (9.5 mm) and any two successive treads shall not deviate in depth by more than 3/16-inch"

and 780 CMR 3603.13.2.1, Nosings:

"Nosings shall not project more than 1 1/2 inches beyond the face of the riser below."

The stairs are not otherwise improperly installed or represent a tripping hazard.

e. Mr. Brett cites no sections of the Code with respect to the railing, and his allegations are vague and do not state a violation of the Code. Mr. Brett does not even allege that railings are required under the Code. Nor does Mr. Brett cite a specific Code provision with respect to handrails. See e.g., 780 CMR 1615.5 (prescribing guardrail and handrail structural loading conditions); 780 CMR 1022.2 (prescribing handrail specifications).

The handrail does not violate the Code.

II. The Absence of Smoke Detectors in the Dwelling's Bedrooms Does Not Violate the Building Code

Mr. Brett alleges that there are no "smoke detectors in the bedrooms." Smoke detectors in bedrooms are required under the current State Building Code only in "one and two family dwellings... constructed" after 1998. 780 CMR 3603.16.1; See also September 1, 2004 State Fire Marshal Advisory, attached hereto as Exhibit E. Homes built prior to 1975 need comply only with G.L. c. 148 § 26E, which require smoke detectors "on each level

of habitation and on the basement level." Exhibit E. The Board of Health may not "impose additional or differing smoke detector requirements." 105 CMR 410.482.


The home was constructed in 1973. Assessor's Field Card is attached hereto as Exhibit F.

Mr. Brett imposes the requirements of 780 CMR 3603.16.13 on the dwelling. That section states that "when one or more sleeping rooms are added or created in existing dwellings, the entire building shall be provided with smoke detectors designed and located as required for new dwellings." No sleeping rooms have ever been added to the dwelling, which is and always has been a four bedroom property. See Exhibit F. The only alteration to the dwelling was a conversion of a garage to an office/workshop in May 1999. Building/Occupancy Permit B99-33 is attached hereto as Exhibit G. At that time the home was inspected and no smoke detector violations were found. See Exhibit G. Consequently, "the lack of installation of non required detectors" cannot serve as a basis for a violation "if the appropriate system has been installed." Exhibit E.

Very truly yours,

Irina V. Temkina

EXHIBIT A



978-468-5585

September 15, 2005

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Irina V. Temkina 125 Neck Road PO Box 4017 Old Lyme, CT 06371

Re:

521 Bridge Street Code Violations

Dear Ms. Temkina:

This letter is in replacement of the letter sent to you on September 12, 2005. On September 12th, the following inspectors met at 521 Bridge Street to inspect the premises for building, electrical and plumbing/gas code violations:

Charles Brett-Building Inspector Robert Brown-Electrical Inspector William Thomas-Plumbing & Gas Inspector

The following are the code violations that were observed to exist:

Building Inspector:

Front stairs from egress improper. 780 CMR 3603.13.2(Treads and Risers) and 780 CMR 3603.13.2.1(Nosings). As you will recall, when I conducted a viewing of the property last August, I observed the front stairs to be in an unacceptably dilapidated state, in violation of the state building code. While the condition of the stairs has changed since then, it remains in a condition that is still in violation. The risers are of non-uniform height and too short. The top step has epoxy affixed to it that constitutes a tripping hazard. It appears that you attempted in the past to affix it in place with the epoxy and when that failed, the top was flipped over and the tread mortared in place with the old epoxy left on. The skim coat on the top step was improperly installed. The nosing represents a tripping hazard. The railing is particularly dangerous, with spacing of the balusters out of code, excessive spacing between the bottom of the railing and the top of the stairs, and bolts loose and inadequate, so that the entire railing can be easily wiggled and is inadequate to support someone's weight.

Inadequate number of smoke detectors. 780 CMR 3603.16.10, .13.

Inadequate number of smoke detectors. 780 CMR 3603.16.10, .13.

Electrical Inspector: There are no GFI outlets in the bathroom. See NEC Article 210.8. It is apparent that there has been work done in this room because a hole that was observed in August next to one of the outlets was no longer present at this latest inspection. When electrical work is performed in an area that is required by Code to have GFI outlets, the existing outlets must be upgraded to GFI outlets. This upgrade has not occurred.

The department is concerned that you have had electrical work done by a person for hire but without applying for an electrical permit, in violation of Mass. Gen. L. c. 143, § 3L. Although an electrician recently obtained a building permit to do work on the premises, the department is aware that earlier this summer you attempted to have electricians perform work but refused to apply for a permit, despite your tenant's ins istence that a permit be obtained as required.

There is only one electrical meter located at this property. This is consistent with the zoning by-law, which prohibits the property from being rented out as more than one dwelling unit.

Plumbing/Gas Inspector:

Faulty mixing valve on shower. 248 CMR 10.10.4. The diverter button between the shower head and the faucet does not work properly.

The hot water heater was installed in a closet that was screwed shut. The closet door should be unscrewed so that inspectors and contractors may access the heater for maintenance, repair and inspection as needed. It is unsafe to leave the heater behind a door that is screwed shut.

I understand that the Health Agent has sent you a letter noting further violations within his purview. This letter is to be viewed in conjunction with those violations.

This inspection occurred at the request of your upper level tenant to follow up on zoning and building code violations that I first observed and notified you about last August. These violations should be corrected within 14 days from receipt of this letter. If you have any further questions, please feel free to contact this office.

Sincerely,

Charles Brett

Inspector of Buildings

Zoning Enforcement Officer

cc: Dawn Goodwin, Beverly Housing Authority

Lori Fonseca, NSCAP

Donna MacKenna, Town Counsel

Bd. Of Health

EXHIBIT B



Town of Hamilton Building Department 577 Bay Road Hamilton, MA 01982 978-468-5585



CERTIFIED MAIL - RETURN RECEIPT REQUESTED

August 19, 2004

Elliot Temkin Irina Temkina 50 Waterside Lane West Hartford, Ct 06107

Dear Sir/Madam:

Please be advised that the property located at 521 Bridge Street, Hamilton, MA., is in violation of several by-law and life safety codes:

Some of which include:

Means of Egress (Blocked)
Smoke Detectors
Water Supply
Electrical Violations
Hand Rails by Main Egress
Number of Bedrooms exceeds Title V System
Illegal Apartment, No Special Permit Obtained from Zoning Board of Appeals
No Anti-Scald Valve in Upstairs Apartment
No GFI Outlets in Bathrooms with Hole Cut in Wall Next to Outlet
Non Payment of Municipal Tax and Water Bills

It is my intention as Zoning Enforcement Officer and Building Inspector to issue a CEASE & DESIST order, and to have the premises vacated by next Tuesday, August 24, 2004. I have advised your tenants to withhold payment of rent until this matter is concluded.

Contact this office immediately so that these unsafe conditions can be corrected.

Regards,

Charles Brett

Inspector of Buildings

Zoning Enforcement Officer

Cc: Board of Health

Fire Department

Police Department

Board of Selectmen

Zoning Board of Appeals

Carles Brett

Enclosures

EXHIBIT C

Statement of Stephen M. Bento

Document 27

I, Stephen M. Bento, swear and affirm that I am a certified Housing Quality Standards Inspector. I have received my training through Mann-McKay. I was employed as Housing Quality Standards Inspector by PHI Inspections, Plymouth, Massachusetts through June 2005. In this capacity. I have conducted HQS inspections for public housing authorities throughout the Commonwealth of Massachusetts.

I inspected Rhonda Baker's unit at 521 Bridge Street, South Hamilton on February 16, 2005 and February 23, 2005. I am familiar with the unit, having inspected it on two occasions prior to February of 2005. The unit passed inspection on February 23, 2005, after the owner corrected minor defects which existed on February 16, 2005, consisting of ripped screens and unfinished surfaces. On February 23, 2005, Ms. Baker's unit was in full compliance with HQS, and I reported this to the Beverly Housing Authority.

Sworn to under pains and penalties of perjury this ____day of September, 2005.

Stephen M. Bento 33 West Avenue

Kingston, MA 02364 (781) 582-0670 (telephone)

(339) 832-3087 (cellular)

Case 1:05-0	×-1	1842-RGS	 (ДС	CUI	mei	nt.27 Filed 10/20/2006 Page 20 of 30	W/\
		E OF FAMILY Bhond	0	<u>///</u>	o r Sal	181 PHONE NO. 7852-2446 TENANT I.D. NO.	
	INSPI	ECTOR				NEIGHBORHOOD/CENSUS TRACT DATE OF INSPECTION	
	<u> </u>	PHI IN		CTIC)NS	2016/05	
استغ	TYPE	OF INSPECTION [Ini	itial	٦ ،	Spe	ocial Annual Other DATE OF LAST INSPECTION	
	-					A OFFICAL DISCOULTES	
•	STRÉ	FT .		· 1,		A - GENERAL INFORMATION CITY COMMENTS HOUSING.T	7. FP9. PP
	0,,,,,	521 Bridg	ا کل	ζ,		Charles an annu	YPE 🐆 🐃
	COUN		STATE	<u></u>		ZIP COJD. (1 Single Family D	• • •
			0.7.1.	10	3	01982 Govo. Semi-Detached	
	NAME	OF OWNER OR AGENT AUTHO	BIZED	TOLEA	SE LINIT	Row House/Tow	n House/
	/	VIAN KOW	1K		<u>a</u>	Duplex	
	ADDR	ESS OF OWNER OR AGENT	11 1		<u></u>	Low Rise	.atau
•	10	5 Coninu	11	RA	5,	High Rise w/ele Manufactured	vator i
•	L'u	5 OKTOUTION	7	1011	<u> </u>	11,300,000	ş
•		·				(10 De completed after form has been tilled out)	
		Pass X Fail	. [clusiv	of the FMR or Payment Standard	
	LP	ASS 2 az	,SS	<u> </u>	SF	3 4	
			-1	-		INSPECTION CHECKLIST	
	пем	TALINING BUOM	VES	A COL	Jak.	DAMEN	FRVAL APPROX
	90		PIS	JAN.	Pagadana	MATTER STATE OF THE STATE OF TH	PARIAL DATE
	1.1	Living Room Present Electricity	1/	+			
	1.3	Electrical Hazards	/		ŀ.	And the second s	
	1.4	Security Window Condition	1	<u> </u>	3		·
	1.6	Celling Condition	1	+			
	1.7	Wall Condition	1		100		
	1.8	Floor Condition Lead-Based Paint	/	-		THARDMOND FOR	
•		Art of pointed surfaces from all deteriorated point? E cot, do deteriorated surfaces exceed and oppore feet per mo- andral is store from 10% of a component?	-	┼──		Z Not Applicable	
	пем	2 Michael		NO.		Service and the service of the servi	FRAL APPROV.
	NO. 2.1	Kitchen Area Present	PASS	EU	COVC	CORPORATION	THE PARTY OF THE P
	2.2	Electricity	1	┼	1 1 1 1	DIM SID	1004
•	2.3	Electrical Hazards	1			la .	
	2.4	Security Window Condition	/	╂	4.0		
	2.6	Celling Condition	(1)				·.
	2.7	Wall Condition	V	X	77.7		2/23/5
	2.9	Floor Condition Lead-Based Paint As all paints successful deteriorate paint I not, to deteriorate faint set per non	-	-	120	TILE NEW	
	L.,	and/or is incre from 10% of a component?			3 44		
	2.10	Stove or Range with Oven Refrigerator	1	ļ	├	Ere('	
	2.12	Sink	5	 	 		
	2.13	Space for Storage and Preparation of Food	7	22500			
	NO.	3. BATHEDOM	YES PASS	NO.	CONC	DOMESTIC	FINAL APPROV
	3.1	Bathroom Present	1	ACCEPTANCE OF THE PARTY OF THE	70	Service Control of the Control of th	MINTER
	3.2	Electricity	1				
	3.3	Electrical Hazards Security	5	-	gaga.		
	3.5	Window Condition	_		180		
	3.6	Celling Condition Wall Condition	1				LE
	3.8	Floor Condition	-	 	100	VINAL GOOD	
	3.9	Lead-Based Paint Are of paints durtured by of detertorsed paint? Brot, to detertorsed surfuse scraed less spare lest per note and/or is more from 10% of a component?			7	A Not Applicable	
	3.10	If not, to detartizated surfaces exceed two square leet per most and/or it more than 10% of a component? Flush Totlet in Enclosed Ploom in Unit	-	<u> </u>	X.75		
	3.11	Found Wash Basin or Levatory in Unit	-		 		
	3.12	Tub or Shower in Unit	_				
	3.13	Ventilation 4. OTHER ROOMS USED:	yro.	- 140	- No.	PORTUGE	Postal Property
	NO.	FOR LIVENS AND HALLS	PASS		CONC.	COMMENT	FMAL APPROV.
	4.1	Room Code* and Room Location	1 0	(Circle	One) F	Nght/Center(Leit) (Circle One) Front/Center(Fleit) Seer Level	· VARGULATE.
	4.2	Electricity/Illumination Electrical Hazards	/	<u> </u>	17.		
	4.4	Security	~			/ 1-11 ma 1	,
	4.5	Window Condition	V	X		MISSING SCREEN & DATE	2/03/05
	4.6	Ceiling Condition Wall Condition	1			/ m 2/16/02	-
	4.8	Floor Condition	2			CARPET GOOD (M)	
	4.9	Lead-Based Paint An all painted particles has of determined paint? If not, the determined particles named has appared feet per room and/or its more than 10% of a component?	-			Car Not Applicable	
	800	.28	ime or			clossing (Departitions of two of wars), (I. C	
	noor	vi CODES 1 = Bedroom pri 2 ≈ Dining Room	or Dini	ng Area	ased for	sleeping (Regardless of type of room) 3 = Second Living Room, Family Room, Den, Playroom, TV Room .5 = Addition 4 = Entrance Halls, Condors, Halls, Staircases 6 = Other	al Bathroom

1023	TEA 4. OTALEE ROOMAE (S NO. STORE FOR EAST HOU	EU .	Yes	110	N.	TOWNER.	FEWAFAPPOU
<u> </u>	4.1 Room Code* and Room L	ocation		Circ	e One)	Right/Center/Lein (Circle One) (Front Cartes/Dear	
	4.2 Electricity/Illumination 4.3 Electrical Hazards		/	Ė	Ľ	Circle One) (Honoyanter/Rear Floor Level	\supset
	4.3 Electrical Hazards 4.4 Security		_	├	200	1 INTOVAL I	+-
	1.5 Window Condition		T)	X	ore or	TORN SCREEN SIVE	1, 1,
	1.6 Ceiling Condition		_			JOHN SCHOOL S	2/28/0
-	.7 Wall Condition .8 Floor Condition	$- \downarrow$	4				4
-			_			CARRET PAIR - STAINS	
L	.9 Lead-Based Paint An all packed curtons the of delerorated paint? Bind, to delerorated purious scraed has against and/or is more than 10% of a component?	bel per room				Al Not Applicable	
4.	1 Room Code* and Room Lor	cation		(Circle	Опа) Г	ight(Cenib)/Leit (Circle One) (Fron)/Center/Rear Floor Level	
1.						(Circle Cite) (PTOT) Center/Hear Finor Level	+—
4.	1,00000				Service 1	TOM TOM	\star
4,		- (7))X	3545	TOOL 500 (50)	} }
4.1				-/-	77	TORN SCREEN / M 5/14/	2/23/55
4.5							<u> </u>
4.5	Lead-Raped Paint		_			CHRIET FAIR - STANS	
L	Art all partial surfaces free of deteriorated paint? 8 tool, to deteriorated surfaces extract any square line ancies is more than 10% of a component?	t per moss	-	- 13	102V2	A) Not Applicable	
4.1	Room Code* and Room Loca	ation \		(Circle (One) Fil	hVCenter/Left (Circle One) Front/Center/Real	
4.2	Electricity/Illumination	\Box	/		Ĭ	pri/Center/Left (Circle One) Front/Center/Rea Floor Level	
4.4					11.150		
4.5		1	ON	= #		20-1201-	
4.6	Ceiling Condition			<u>ع ا</u>		PRINTE SLIDING GUASS DOUR - FAIL-PAS MISSING SCREEN ON SLIDER	2/03/05
4.7	Wall Condition	C	"))	X a		INFINISHED SURFACE	61
4.8	Floor Condition		1			TARPHO OCO MENA	7183 VZ
L	Lead-Based Paint An all pained parkets has of deteriorated paint? West, to deteriorated parkets accorded to square heat p and/or is more fame 10% of a component?	W 5003	+			8 Not Applicable	
'RC			other -	DOM	nd to	police (Described	
क्षामान	2 = Dining R	oom, or	Dining	Area	HA TOT EN	seping (Regardless of type of room) 3 = Second Living Room, Family Room, Den, Playroom, TV Room 5 = Addition 4 = Entrance Halls, Corridors, Halls, Staircases 6 = Other	nal Bathroom
	D. ALL SECONDARY ROOMS	l VI	8			G = Oiner	Sampana
5.1	NONE IS Go to Part 6	2.23				SCHWING	FRVAL APPRIOR. ONTIAL/DATE
5.2	Security Security	- 30	37		100		
5.3	Electrical Hazards		+	╌┞╴			
5.4	Other Polantially Hazardous Final-ree in any of These Ro	cons.		\dashv	\dashv		
THE	A SECULORIC EXTERNOR	1		W. D	Y.	Spinop)	A HERBERTHANDS
6.1	Condition of Foundation	PA	8	W. P.	W. E.	TOWNS	TINAL APPROV. With that
6.2	Condition of Stairs, Rails, and Porch	es /	,-		216		
6.3	Condition of Roof and Gutters	15	+				
6.4	Condition of Exterior Surfaces					- t	
6.6	Condition of Chimney	1-	4	200	選		
. :	Lead Paint: Exterior Surfaces An at parted nutices the of detertioned paint? End, to described surfaces second 20 square less of a total orderic curicus area?	-	+		湖上	Not Applicable	
6.7	Manufactured Homes: Tie Downs	1	+	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	P	Not Applicable	
6.8	Manufactured Homes: Smoke Detect	ors .		185		Not Applicable .	
HEM	THEATING B. PHIMITING						Districtor (Statement)
7.1	Adequacy of Heating Equipment		i i	5 (70)	315 000.75		TVAL APPROV. Intralidate
7.2	Safety of Heating Equipment	1	+-	+	16		and the same
7.3	Ventilation/Cooling	15	+	+	+		i
7.4	Water Heater		1		1=	17	
7.5 7.6	Approvable Water Supply Plumbing	1	\Box				
7.7	Sewer Connection	15	+		4		
UEV.	O GENERAL HEALTH		ngs.	Marie V	建筑原		
W	AND SAFETY	7838		GON		ALL MARIE CONTRACTOR OF THE PROPERTY OF THE PR	VAL APPROV.
8.1	Access to Unit		2	2.5	4		VIIIA DATE
8.2 8.3	Fire Exits	-					
8.4	Evidence of Infestation Garbage and Debris	 	_				
8.5	Refuse Disposal	15	1-	396	4		
3.6	Interior Stairs and Common Halis			+	+-		
8.7 8.8	Other Interior Hazards			24			
B.9	Elevators Interior Air Quality	<u> </u>		150.00		lot Applicable	
3.10	Site and Neighborhood Conditions		<u> </u>	1	i i		
3.11	Smoke Detectors on Every Level			77.10	-		
3.12	Lead Paint: Owner Certification				10 N	ol Applicable	
.12	LEAD PAINT: OWNER CERTIFICA	ATION		- In Carrier 1744			
the ou	What is remilired to come a and		sed pa	aint haz	ards at	the property including deteriorated paint or other hazards identified by a visual assessor, a certified lead-bas t obtain certification that the work has been done in accordance with all applicable conductions.	
on ass he Lea	ad-Based Paint Owner Certification	aint inš	pector	r, the Pl	lÁ mus	the property including deteriorated paint or other hazards identified by a visual assessor, a certified lead-bas t obtain certification that the work has been done in accordance with all applicable requirements of 24 CFR F PHA before the execution of the HAP contract or within that time period could be the DNA leaf.	ed paint
otice. I	Receipt of the completed and s	iguég Pi moréitin	ead-B	ased Pa	i by the lint Ow	t obtain certification that the work has been done in accordance with all applicable requirements of 24 CFR F PHA before the execution of the HAP contract or within the time period stated by the PHA in the owner HQS ner. Certification signifies that all HQS lead-based paint requirements have been met and no re-inspection by	violation
specto	or is required.	<u> </u>				based paint requirements have been met and no re-inspection by	the HQS
	•					A1/1 Q1 0 1.16)	
	Ę.				14.00	(J	

1.

Signature Langing Magarit Signature

Inspectors Signature

2/16/57

EXHIBIT B

Filed 10/20/2006

Page 23 of 30

× 22

FIRE & LIFE SAFETY INSPECTION





Hamilton Fire Department 265 Bay RD Hamilton, MA 01982

Inspection Notice CONSULTATION - Fire Alarm

(EX #3)

February 28, 2006

521 Bridge Street 521 BRIDGE ST Occupancy ID: BRID0521

Hamilton, MA 01982

An inspection of your facility on February 28, 2006

revealed the violations listed below.

In accordance with Massachusetts General Laws (MGL), (Terr. Ed. as amended) Chapter 148, Sections 9, 10, 108, 15, 380, 38E, 38G, 38H,

and Board of Fire Prevention regulation, 527 CMR Code of Massachusetts Regulation as amended

We will re-inspect for compliance on/or after

Code	Location	Number
148.28.A Violation of Building Code The head of the fire department or any perso observes any condition which he believes to amendments thereto, shall report the same to	be a violation of any provision of th	e state building code or any
1.06.5 Building Code Violations The head of the fire department or any perso observes any condition which he believes to to the authority charged with the enforcement Upon a request of the owner an inspection w (5) bedroom located on the lower level off the second kitchen located in the lower level. At the dwelling. This would require at a minimum has outside the bedroom areas, and possibly in experience.	be a violation of any provision of 78 t of such provision. (M.G.L. c. 148, was conducted on 28-2-06, it was called a large room left of the base of the shis time I am in the opinion that thind wired interconnected smoke defined to the smoke defined the smoke defined wired interconnected smoke defined the smoke define	30 CMR, shall report the same § 28A). Iiscovered that there was a fith staircase. There was also a s is set-up as a two (2) family
	For your records	
Parsons, Daniel E Inspector	Irina Temkina Occupant/Manage	er/Owner

Page

08:37

EXHIBIT C





Mitt Romney Governor

Kerry Healey Lieutenant Governor

> Robert C. Haas Secretary

The Commonwealth of Massachusetts Department of Public Safety

Board of Building Regulations and Standards
One Ashburton Place, Room 1301
Boston, Massachusetts 02108-1618
Phone (617) 727-3200
Fax (617) 227-1754

Thomas G. Gatzunis, P.E. Commissioner

> Gary Moccia Chairman

Stanley Shuman Vice Chairman

Robert Anderson Deputy Administrator

STATE BUILDING CODE APPEALS BOARD

Date:

April 6, 2006

Name of Appellant:

Irina Temkina

Service Address:

125 Neck Road, P.O. Box 4017

Old Lyme, CT. 06371

In reference to:

Docket Number:

05-193

Property Address:

10 Industrial Court

Seekonk, MA. 02771

Date of Hearing:

February 28, 2006

We are pleased to enclose a copy of the decision relative to the above case wherein certain variances from the State Building Code had been requested.

Sincerely:

STATE BUILDING CODE APPEALS BOARD

Vaticula (Damy Patricia Barry, Clerk)

cc:

State Building Code Appeals Board

BBRS Program Manager

COMMONWEALTH OF MASSACHUSETTS BUILDING CODE APPEALS BOARD

In the Matter of:

528 Bridge Street, South Hamilton, MA

Docket Number:

05-193

Appellant:

Irina Temkina

Hearing Date:

February 28, 2006

Present:

Irina Temkina, Elliott Tiomkin, Charles Brett, Debra Paskowski,

Keith Hoyle, Harry Smith, Brian Gale and Patricia Barry

INTRODUCTION

Pursuant to M.G.L. Ch. 143, section 100, M.G.L. Ch. 30A, and 801 CMR 1.02 and 1.03, a hearing was held before the Building Code Appeals Board (the "Board") in Wellesley, Massachusetts on February 28, 2006, to consider the appeal of Irina Temkina (hereinafter referred to as "Appellant"). The Appellant, the Hamilton Building Commissioner and the Hamilton Fire Department were notified of the hearing by first class mail sent February 16, 2006.

All witnesses were duly sworn at the start of the hearing. The proceedings were recorded, and the digital sound recording of the proceeding is available at the Office of the Board, in the Department of Public Safety, upon request and reasonable advance notification. The following findings and conclusions are based upon the testimony and documents offered by the witnesses, as well as the administrative records of the Board.

FINDINGS OF FACT

- 1. The Appellant is Irina Temkina, having an address of 125 Neck Street, Old Lyme, Connecticut.
- 2. The property affected by this Decision is located at 521 Bridge Street in Hamilton, Massachusetts.
- 3. Appellant is appealing a finding of Building Code Violations made by the Building Department from the Town of Hamilton dated September 15, 2005. They were: improper egress on front stairs as to treads and risers (780 CMR (Sixth Edition) section 3603.13.2), improper nosings (section 3603.13.1), lack of proper handrail (section 3603.14.1.1), and inadequate number of smoke detectors on site (section 3603.16.10).

- 4. The property is a residence owned by the Appellant which is presently being leased to a single family, i.e., a mother and her three children.
- 5. Appellant and her family lived at the premises for a time in 1999. Prior to moving out, the Appellant caused to be converted the garage into a kitchen and a room described by the Appellant's son as an "office workshop."
- 6. Notwithstanding the sugar coating, the "office workshop" was used as a bedroom while the Appellant rented out the premises to two separate tenants, the "upstairs" tenant and the "downstairs" tenant, for an approximate one-year period.
- 7. It is Appellant's view now that whatever conditions existed in the past, in its present incarnation, the premises are being used as a single-family residence.
- 8. With respect to the issue of the stairs, the testimony of the Appellant's son was self-contradictory. He testified that when they first purchased the house, there was no railing on the exterior stairway. He then testified that "we" removed the railing because it was improperly installed. Photographs from 2004, show a railing on one side of the stairway, but a photograph of the stairway as it currently exists shows no railing.
- 9. A report from the Hamilton Fire Department dated February 28, 2006 (the same day that the hearing was conducted), states that as of the day of the inspection "it was discovered that there was a fith (sic) (5) bedroom located on the lower level off the large room left of the base of the staircase. There was also a second kitchen located in the lower level." The conclusion of the inspector of the Hamilton Fire Department was "that this was set-up as a two (2) family dwelling. This would require at a minimum hard wired interconnected smoke detectors on all levels and outside the bedroom areas, and possibly in every bedroom."

CONCLUSION AND ORDER

While the Hamilton Fire Department is in no better position than the Building Department to make a finding of fact concerning whether a structure is useable as a two-family dwelling, the report of February 20, 2006, simply confirms the testimony of the Appellant's son that at times in the past there were two separate tenants leasing this structure. The Appellant did not offer any testimony as to what the reason would be for the addition of a kitchen to a structure that previously functioned as a single-family residence, other than, which the Board infers, for the creation of a second rental unit. The railing on the stairway which was observed by the Building Department on September 12, 2005, to be "particularly dangerous, with spacing of the ballusters out of code, excessive spacing between the bottom of the railing and the top of the stairs, and bolts loose and inadequate, so that the entire railing can be easily wiggled and is inadequate to support someone's weight," was simply removed by the Appellant prior to the time that the inspection was made and the hearing was conducted. That is not an adequate response to

the violation notice.

Accordingly, upon motion made and duly seconded it was unanimously:

Voted, to uphold the order of the Inspector of Buildings dated September 15, 2005, with respect to the inadequacy of the front stairs concerning treads and risers (780 CMR (Sixth Edition) 3603.13.2), nosings (Section 3603.13.2.1), and handrail (Section 3603.14.1.1), and also based on the inadequate number of smoke detectors in accordance with Section 3603.16.10, 13.

SO ORDERED,

KEITH HOVLE

BRIAN GALE

DATED: April 6, 2006

In accordance with MGL, Chapter 30A, Section 14, any person aggrieved by this decision may appeal the decision to a court of competent jurisdiction within 30 days.

EXHIBIT D

Mitt Romney

Governor

Kerry Healey
Lieutenant Governor

Case 1:05-cv-11542-RGS Document 27 Filed 10/20/2006 Page 30 of 30 The Commonwealth of Massachusetts

Department of Public Safety
One Ashburton Place, Room 1301

One Ashburton Place, Room 1301
Boston, Massachusetts 02108-1618
Phone (617) 727-3200
Fax (617) 727-5732

Edward A. Flynn Secretary

Thomas G. Gatzunis, P.E. Commissioner

March 7, 2006

Donna Brewer MacKenna Casner & Edwards, LLP 303 Congress Street Boston, MA 02210

Re: Public Records Request

Dear Ms. MacKenna,

Enclosed please find documents responsive to your request for a copy of the file on Massachusetts State Building Code Appeal #05-193 regarding 521 Bridge Street, So. Hamilton, MA.

Sincerely,

Todd M. Grossman Deputy General Counsel